


HD100 – Quick Card



- 1 ON (On/measuring) button
- 2 Plus (+) button
- 3 Minus (-) button
- 4 Area/Volume button
- 5 Indirect measurement (Pythagoras) button
- 6 Reference button
- 7 Function button
- 8 Timer button
- 9 Storage button
- 10 Menu / Equal button
- 11 Clear / Off button

